


FT 420 (MILLIAMPER OUTPUT ONLY)

APPLICATION BRIEF

WIRING DIAGRAM

FT 420



NOTES

1. Consult IOM-035 for transmitter specifications and power supply requirements.
2. Insulate ends of unused wires with electrical tape.



BadgerMeter, Inc.

P. O. Box 245036 Milwaukee, WI 53224-9536
Telephone: (414) 355-0400
Fax: (414) 355-7499