


FT-420 SERIES TRANSMITTERS & 3000 SERIES CHART RECORDER

APPLICATION BRIEF

WIRING DIAGRAM



Notes:

1. Calibrate transmitter output so 20 mA is equal to maximum flow of system.
2. Calibrate recorder so 20 mA input corresponds to full scale.



BadgerMeter, Inc.

P. O. Box 245036 Milwaukee, WI 53224-9536
 Telephone: (414) 355-0400
 Fax: (414) 355-7499